



PRODUCT CHANGE NOTICE

JANUARY 18TH, 2009

Notification Number	09-00454-00
Change Subject	A4500-CPU-OEM & A4500-CPU-Base
Type of Change	Minor Changes to Form Fit or Function
Key Milestone	Customers must be ready to receive changed product by February 24th

Change Description:

1. Remove plastic pull tab on memory cover to avoid any potential issue with plastic tab catching on chassis during insertion or removal.
2. Shorten length of thumb screw to avoid an issue of the thumb screw not fully extracting from some specific vendor's chassis. Thumb screw length will change from 2.5mm to .8mm, as measure from the front of the face plate to the end of the screw when fully retracted
3. Add thread locking compound to top cover screws with the exception of the screws on the memory cover.

Customer Impact & Recommended Action:

There is no customer impact

Product Codes Affected

Product Code	Old TA #	New TA#
A4500-CPU-Base	067-10609-005	067-10609-006
A4500-CPU-OEM	067-10786-001	067-10786-002

Revision History

Revision #	Date	Revision Description
00	1/18/2009	First Revision



If you have questions or concerns with the content of this change notice, please contact the RadiSys Representative(s) for your geographic location or you can visit www.radisys.com and go to "Contact Us" , which provides a complete list of RadiSys Global Sales Offices and Channel Partners.